



$q = 4 (\cos 36,87^\circ)^2 = 2,56 \text{ kN/m}^2$   
 $M = 4 \cdot \cos 36,87^\circ \cdot \sin 36,87^\circ = 1,92 \text{ kN/m}^2$



